

# MOUNT TODD GOLD MINE

**Monthly Discharge Monitoring Report  
December 2020  
WDL 178-08**

**Prepared for:**

Vista Gold Australia Pty Ltd  
Level 1 Cavenagh Centre  
43 Cavenagh Street  
DARWIN NT 0800

SLR Ref: 680.10533.00400-R01  
Version No: -v1.0  
January 2021

**SLR** 

## PREPARED BY

SLR Consulting Australia Pty Ltd  
ABN 29 001 584 612  
Unit 5, 21 Parap Road  
Parap NT 0820 Australia  
(PO Box 1300 Parap NT 0804)  
T: +61 8 8998 0100  
E: darwin@slrconsulting.com www.slrconsulting.com

## BASIS OF REPORT

This report has been prepared by SLR Consulting Australia Pty Ltd (SLR) with all reasonable skill, care and diligence, and taking account of the timescale and resources allocated to it by agreement with Vista Gold Australia Pty Ltd (the Client). Information reported herein is based on the interpretation of data collected, which has been accepted in good faith as being accurate and valid.

This report is for the exclusive use of the Client. No warranties or guarantees are expressed or should be inferred by any third parties. This report may not be relied upon by other parties without written consent from SLR.

SLR disclaims any responsibility to the Client and others in respect of any matters outside the agreed scope of the work.

## DOCUMENT CONTROL

Reference	Date	Prepared	Checked	Authorised
680.10533.00400-R01-v1.0	28 January 2021	Slavica Kandic	Loren Yallop	Jill Woodworth

## CONTENTS

<b>1</b>	<b>INTRODUCTION .....</b>	<b>4</b>
1.1	Background .....	4
1.2	Site .....	4
1.3	WDL Requirements .....	4
<b>2</b>	<b>WATER QUALITY.....</b>	<b>6</b>
2.1	Discharge dates.....	6
2.2	Water quality data .....	7
<b>3</b>	<b>DISCUSSION OF SSTV EXCEEDANCES .....</b>	<b>8</b>
3.1	Metal exceedances .....	8
3.2	Management actions – 31 December 2020.....	8
<b>4</b>	<b>MT TODD WATER INVENTORY .....</b>	<b>9</b>

## DOCUMENT REFERENCES

### TABLES

Table 1 Mt Todd December Discharges.....	6
Table 2 Water quality summary for December 2020 Discharges .....	6
Table 3 Water inventory December 2020 .....	9

### APPENDICES

Appendix A Incident Report

# 1 Introduction

## 1.1 Background

This Monthly Discharge Report details the results of water quality monitoring undertaken during discharge of treated water during December 2020 from Batman Pit to the Edith River at the Mount Todd Gold Mine. The Monthly Discharge Report is a requirement of Waste Discharge Licence (WDL) 178-08 issued by the Northern Territory Environment Protection Authority (NT EPA) under section 74 of the NT *Water Act*.

## 1.2 Site

The Mount Todd Gold Mine is located within the Daly River Catchment area in the Northern Territory. The Edith River is located directly to the south of the mine site and intersects Mineral Lease Number (MLN) 1127. The Edith River is the largest of various tributary rivers and creeks to the Fergusson River, which ultimately flows into the Daly River.

The Edith River has a high ecological and recreational value, with the mine site located approximately 9 km downstream of Edith Falls situated within Nitmiluk National Park. The Edith River is fed by several ephemeral creeks, five of which run through the Mt Todd mine site and currently receive runoff from site related catchments within the mineral leases. The regional drainage pathway and catchment plan of the Edith River sub-catchment is described in detail in the Mount Todd Gold Mine Water Management Plan (WMP 2020).

Vista Gold Australia Pty Ltd (Vista Gold) have operated the care and maintenance phase of the Mount Todd Gold Mine since 2006; the site was previously mined for gold during the 1990s before its closure in 2000. Vista Gold's water management strategy for the Mount Todd Gold Mine respects that water management is an integral part of managing the mine site and its interaction with the surrounding environment. In accordance with their objectives Vista Gold have adopted an integrated multiple lines of evidence approach to manage the environmental impacts from active and passive discharges entering the Edith River, including water quality, macroinvertebrate, ecotoxicology and sediment monitoring programs.

Vista Gold's water management strategy includes onsite storage, treatment and licenced water discharges, to reduce the risk of uncontrolled discharges offsite. Water is treated in-situ within Batman Pit prior to active discharge. Discharge of treated water only occurs during the wet season, to manage additional inputs from rainfall, ensure integrity of site water storages, and minimise the risk of uncontrolled discharge.

## 1.3 WDL Requirements

WDL 178-08 licences Vista Gold to discharge treated water from Batman Pit into the Edith River, subject to conditions. The licence was granted on 30 November 2020, and is valid until 30 November 2022. The licence allows for active discharge of treated water from the Batman Pit (RP3), at the authorised discharge point, from where it flows to the Edith River via Stow Creek. The compliance monitoring point is SW4, which is downstream of the mine and receives flow from the upstream Edith River catchment.

This report has been prepared to fulfil Condition 50 of WDL 178-08, being:

*"50 - The licensee must submit to the Administering Agency a Monthly Discharge Report for any month when a discharge occurs via the authorised discharge point by emailing [waste@nt.gov.au](mailto:waste@nt.gov.au). The Monthly Discharge Report is due by the last business day of the following month and must include:*

- 50.1. *tabulated water quality data for RP3 and SW4 for each day of the month where a discharge occurred. Data must be provided electronically in Microsoft Excel format;*
- 50.2. *tabulated daily environmental field data, relating to the particular month, for SW4 and RP3 (Batman Pit) as required in Appendix 1. Data must be provided electronically in Microsoft Excel format;*
- 50.3. *tabulated water quality data for all monitoring locations associated with this licence and specified in Appendix 1. Data must be provided electronically in Microsoft Excel format;*
- 50.4. *surface water quality management actions taken in the event of trigger value exceedance measured at SW4;*
- 50.5. *assessment of surface water monitoring results for SW4 against the SSTVs specified in Appendix 1;*
- 50.6. *where SSTVs were exceeded an assessment of the environmental impact, resulting from the discharge activity and exceedances, on the receiving environment at SW4; and*
- 50.7. *details of current water inventory on site.”*

## 2 Water Quality

### 2.1 Discharge dates

Vista Gold actively discharged treated water from Batman Pit in December 2020. **Table 1** shows the dates and volumes of discharge of treated water from Batman Pit.

**Table 1 Mt Todd December Discharges**

Dates of discharge	Number of days discharging	Average discharge rate per day (L/s)	ML Discharge (ML)
14-16 Dec	3	70	18.19
18-31 December	14	436.78	528.33
<b>Total</b>	<b>18</b>	<b>Total</b>	<b>547.34</b>

Water quality monitoring is undertaken in accordance with Appendix 1 of Waste Discharge Licence (WDL 178-08). Monitoring locations, frequency and parameters are outlined in the WDL. This report, consistent with Condition 50 of the WDL, focusses on water quality data from RP3 (Batman Pit), SW2 (upstream in Edith River) and SW4 (compliance point in Edith River). The results of monitoring which occurred at these three points over the reporting period is summarised in **Table 2** to meet the requirement of the following condition:

*Condition 50.5. assessment of surface water monitoring results for SW4 against the SSTVs specified in Appendix 1;*

**Table 2 Water quality summary for December 2020 Discharges**

Analyte	SW4 SSTV	14-December 2020			21 December 2020			28 December 2020		
		SW2	SW4	RP3	SW2	SW4	RP3	SW2	SW4	RP3
<b>Dissolved metals</b>										
Aluminium (µg/L)	150	50	40	50	50	10	40	100	20	1,800
Cadmium (µg/L)	0.8	0.1	0.1	9.4	0.1	0.3	8.6	0.1	0.4	20
Cobalt (µg/L)	13	1	1	24	1	1	29	1	2	97
Copper (µg/L)	2.5	1	1	7	1	1	19	1	6	550
Chromium (µg/L)	-	1	1	1	1	1	1	1	1	1
Iron (µg/L)	350	200	230	10	470	110	10	300	130	880
Lead (µg/L)	9.4	1	1	1	1	1	1	1	1	7
Manganese (µg/L)	3,600	12	19	470	13	54	550	8	58	1,300
Nickel (µg/L)	17	1	1	72	1	3	80	1	4	150
Zinc (µg/L)	31	7	11	360	1	29	590	3	63	3,000
<b>Major ions</b>										
Bicarbonate (mg/L)	319	8	8	17	6	9	15	10	8	5
Chloride (mg/L)	64	2	2	8	4	5	9	2	2	7
Magnesium (mg/L)	21	1.1	1.6	200	0.8	10	200	0.8	5.9	190
Sulphate (mg/L)	129	1	5	2,000	1	90	2,000	1	43	1,900

Analyte	SW4 SSTV	14-December 2020			21 December 2020			28 December 2020		
		SW2	SW4	RP3	SW2	SW4	RP3	SW2	SW4	RP3
Total Cyanide (µg/L)	0.007		<0.004			<0.004		<0.004	<0.004	<0.004
<b>Water discharge characteristics</b>										
EC (µS/cm)	250	31	44	3,123	23	239	3,015	25	157	3,000
pH	6.0- 8.0	6.2	6.3	7.1	6.4	6.2	7.0	6.3	6.3	4.8
Temperature (°C)	-	30	29	33	29	28	32	30	29	30
DO (mg/L)	-	6.9	6.9	6.9	6.9	6.9	7.5	5.4	6.7	7.2
DO (%saturated)	85- 120	93	90	98	91	89	103	85	88	96
1. Water discharge characteristics data were not available for treated water.										
Site specific trigger value										

Note: Shaded cells denote an exceedance of the SSTV at SW4.

## 2.2 Water quality data

An excel spreadsheet containing water quality data from the Mt Todd site during December 2020 has been supplied to the regulator with this report to meet the following conditions of WDL 178-08:

*Condition 50.1. tabulated water quality data for RP3 and SW4 for each day of the month where a discharge occurred. Data must be provided electronically in Microsoft Excel format;*

*Condition 50.2. tabulated daily environmental field data, relating to the particular month, for SW4 and RP3 (Batman Pit) as required in Appendix 1. Data must be provided electronically in Microsoft Excel format;*

*Condition 50.3. tabulated water quality data for all monitoring locations associated with this licence and specified in Appendix 1. Data must be provided electronically in Microsoft Excel format;*

## 3 Discussion of SSTV exceedances

### 3.1 Metal exceedances

As shown in **Table 2**, copper and zinc exceeded the SSTV at SW4 on 28 December 2020. Dissolved copper was measured at 6 µg/L and dissolved zinc was measured at 63 µg/L. The copper concentration triggered a non-compliance of WDL 178-08 under Condition 47.2 of WDL 178-08 as it was greater than two times the SSTV of 2.5 µg/L. The zinc exceedance did not trigger a non-compliance of the WDL.

Vista Gold provided the NT EPA an Incident investigation report on the copper exceedance and subsequent zinc exceedance recorded in January (not discussed in this monthly report) on 18 January 2021 after additional samples were taken to confirm the exceedances.

To meet the following condition of WDL 178-08:

*Condition 50.6. where SSTVs were exceeded an assessment of the environmental impact, resulting from the discharge activity and exceedances, on the receiving environment at SW4;*

Environmental impacts resulting from the SSTV exceedances are considered unlikely as evidenced by historical macroinvertebrate and ecotoxicology results sampled after similar metal exceedances. Further, this conclusion is supported by the 2020 macroinvertebrate, sediment and ecotoxicology data, which indicates that discharge of water from Batman Pit at current dilution ratios is not having a measurable impact on aquatic ecosystem health downstream of the mine site.

### 3.2 Management actions – 31 December 2020

This section describes the management actions taken to meet the following WDL 178-08 condition:

*Condition 50.4. surface water quality management actions taken in the event of trigger value exceedance measured at SW4;*

Management actions were implemented by Vista Gold immediately upon receipt of the analytical results from the laboratory on 31 December 2020. The following actions were undertaken:

1. Vista Gold contacted the laboratory to confirm the results.
2. The dilution ratio was immediately changed from 1:25 to 1:168.
3. The water sampling frequency was increased to two - three times a week to improve monitoring resolution.



## 4 Mt Todd Water Inventory

**Table 3** is provided to meet the WDL 1787-08 condition 50.7 below and gives an approximate estimate of the water inventory on site:

*Condition 50.7. details of current water inventory on site.*

**Table 3 Water inventory December 2020**

Date	RP1 (GL)	RP3 (Batman Pit) (GL)	RP7 (GL)	Total (GL)
1 December 2020	0.769	2.12	2.17	5.059
31 December 2020	0.881	1.685	2.690	5.256
Difference	0.112	-0.435	0.52	0.197

Note: the total for the Batman Pit reduction is estimated at 0.435 GL and the measured discharge shown in **Table 1** is 0.55 GL. This variation may be due to water from other sources entering the pit - including rainfall and ingress.

# APPENDIX A

Incident Report

## ASIA PACIFIC OFFICES

### BRISBANE

Level 2, 15 Astor Terrace  
Spring Hill QLD 4000  
Australia  
T: +61 7 3858 4800  
F: +61 7 3858 4801

### CANBERRA

GPO 410  
Canberra ACT 2600  
Australia  
T: +61 2 6287 0800  
F: +61 2 9427 8200

### DARWIN

Unit 5, 21 Parap Road  
Parap NT 0820  
Australia  
T: +61 8 8998 0100  
F: +61 8 9370 0101

### GOLD COAST

Level 2, 194 Varsity Parade  
Varsity Lakes QLD 4227  
Australia  
M: +61 438 763 516

### MACKAY

21 River Street  
Mackay QLD 4740  
Australia  
T: +61 7 3181 3300

### MELBOURNE

Level 11, 176 Wellington Parade  
East Melbourne VIC 3002  
Australia  
T: +61 3 9249 9400  
F: +61 3 9249 9499

### NEWCASTLE

10 Kings Road  
New Lambton NSW 2305  
Australia  
T: +61 2 4037 3200  
F: +61 2 4037 3201

### NEWCASTLE CBD

Suite 2B, 125 Bull Street  
Newcastle West NSW 2302  
Australia  
T: +61 2 4940 0442

### PERTH

Ground Floor, 503 Murray Street  
Perth WA 6000  
Australia  
T: +61 8 9422 5900  
F: +61 8 9422 5901

### SYDNEY

Tenancy 202 Submarine School  
Sub Base Platypus  
120 High Street  
North Sydney NSW 2060  
Australia  
T: +61 2 9427 8100  
F: +61 2 9427 8200

### TOWNSVILLE

12 Cannan Street  
South Townsville QLD 4810  
Australia  
T: +61 7 4722 8000  
F: +61 7 4722 8001

### WOLLONGONG

Level 1, The Central Building  
UoW Innovation Campus  
North Wollongong NSW 2500  
Australia  
T: +61 2 4249 1000

### AUCKLAND

Level 4, 12 O'Connell Street  
Auckland 1010  
New Zealand  
T: 0800 757 695

### NELSON

6/A Cambridge Street  
Richmond, Nelson 7020  
New Zealand  
T: +64 274 898 628